




00792482

THIS RECORDER SHOWS TO BE OUT  
OF CALIBRATION ACCORDING TO MUD  
WEIGHT 50.00 ON TICKET.



## CHARGES

B-198

Test at \_\_\_\_\_, \$  
Misrun at \_\_\_\_\_, \$  
Rental on Tools \_\_\_\_\_—16 Hours at \$2.50  
Safety Joint \_\_\_\_\_  
Dual Wall Packers \_\_\_\_\_  
Testing Between Two Packers \_\_\_\_\_  
Service Charge \_\_\_\_\_  
Mileage Charge \_\_\_\_\_ Mls. at \_\_\_\_\_¢  
Jars \_\_\_\_\_  
Operators' Time \_\_\_\_\_—16 Hours at \$2.50  
Reservoir Sampler \_\_\_\_\_  
Damaged Rubber Packer \_\_\_\_\_ X

B-360

## SUBSURFACE PRESSURE DATA

	Field Reading		Corrected Reading	
	TOP	BOTTOM	TOP	BOTTOM
Recorder No.			B-198	B-360
Initial BH Flow			80	70
Final BH Flow			30	70
Max. Recorded Shut In			1420	1180
Initial Hydrostatic			3700	3000 <del>+</del>
Final Hydrostatic			3700	3000 <del>+</del>