

**OIL AND GAS CONSERVATION COMMISSION**  
**DEPARTMENT OF NATURAL RESOURCES**  
**OF THE STATE OF COLORADO**

File in duplicate for Patented and Federal lands.  
 File in triplicate for State lands.



COLO. OIL &amp; GAS

5. LEASE DESIGNATION AND SERIAL NO.

GAS CONS. COMM.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

UPRR Tippet

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

WC

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 17: T3S, R61W.

12. COUNTY

Adams

13. STATE

CO

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
 Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Rincon Operating - Morgan Oil Co.

3. ADDRESS OF OPERATOR

1580 Lincoln St. #700, Denver, CO 80203

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
 See also space 17 below.)

At surface

At proposed prod. zone CSWSE

Drilled on a stright hole

14. PERMIT NO.

801494

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5117 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:


WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT ☒

(Note: Report results of multiple completion on Well  
 Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work 12/6/80

- Hole filled w/9.9 PPG Drilling Mud
- Spot 30sx cmt plug in bottom of surface casing
- Fill surface casing w/9.9 PPG mud
- Place 5sx cmt at top of surface casing
- Cut off surface casing at weld on plate.



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent

DATE 12/15/80

(This space for Federal or State office use)

APPROVED BY

TITLE

DIRECTOR  
O&G CONS. COMM.

DATE DEC 16 1980

CONDITIONS OF APPROVAL, IF ANY: