

Smith Wolter B1

document number 702500313

Date completed 8/16/2022

Repaired erosion channels on cut bank and added a berm on the edge of location to direct water around the pad.

Repaired road

