

**Inspection Photos  
Rodgers #1 Flowline  
Spill ID 482755**



**Photo 1 – Spill location 8/15/2022.**



**Photo 2 – Hydrovaced excavation 8/15/2022.  
Flowline exposed and hydrocarbons observed in-situ and on water in excavation.**



**Inspection Photos  
Rodgers #1 Flowline  
Spill ID 482755**



**Photo 3 – Spill location 8/17/2022.**



**Photo 4 – Hydrovaced excavation 8/17/2022 at spill area. Flowline exposed and hydrocarbons observed in-situ and on water in excavation.**



Inspection Photos  
Rodgers #1 Flowline  
Spill ID 482755



**Photo 5 – Site photo showing both excavation areas**



**Photo 6 – Operator personnel observed hydrovacing on location (8/17/2022) ~120 east of spill location.**



**Inspection Photos  
Rodgers #1 Flowline  
Spill ID 482755**



**Photo 7 – Cigarette butt at 8/17/2022 hydrovaced location.**




**Photo 8 – Cigarette butt at 8/17/2022 hydrovaced location.**



Inspection Photos  
Rodgers #1 Flowline  
Spill ID 482755



Inspection Photos  
Rodgers #1 Flowline  
Spill ID 482755





Inspection Photos  
Rodgers #1 Flowline  
Spill ID 482755

