

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403141996

Date Received:

08/19/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

De Paolo, Corey

corey.depaolo@state.co.us

.TEP

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 699804725

Inspection Date: 07/22/2022

FIR Submit Date: 07/25/2022

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335230

Location Name: DOE-66S95W Number: 21SESW County: _____

Qtrqr: SESW Sec: 21 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.505209 Longitude: -108.006764

FACILITY - API Number: 05-045- -00 Facility ID: 335230

Facility Name: DOE-66S95W Number: 21SESW

Qtrqr: SESW Sec: 21 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.505209 Longitude: -108.006764

CORRECTIVE ACTIONS:

1 ☒ CA# 163519

Corrective Action: Oil and Gas Locations will be kept free of all Undesirable Plant Species.

Date: 08/01/2022

Response: CA COMPLETED

Date of Completion: 07/29/2022

Operator Comment: weeds within the containment have been removed and area sprayed to prevent regrowth of undesired species

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 163520

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 08/09/2022

Response: CA COMPLETED

Date of Completion: 08/08/2022

Operator Comment: Areas affected by gully erosion has been repaired with road base material and rolled. Rubber wattles have been installed to prevent further gully erosion from occurring, as well as gravel added to the road to prevent rilling.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA's have been corrected and areas affected repaired

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Kris Rowe

Signed:

Title: TEP Env

Date: 8/19/2022 1:38:13 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403141996	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files