



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	Adequate		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	Weeds around the well needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	08/26/2022

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

**Equipment:**

	#		corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 250895 Type: WELL API Number: 123-18698 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 03/27/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Wednesday 8/17/22 at approximately 0745hrs, I, Inspector Adam Burns,                      Conducted an on-site inspection at Lyster E 26-15 of Chevron, at                      API # 05-123-18698 in Weld County, Colorado.                      During this inspection the following possible compliance issues were observed:                      Weeds around the well needs to be removed for good housekeeping. Comply with Rule                      606. With a corrective action date of 8/26/22                      See attached photo.                      Submit pictures on FIRR.                      A follow up on this site inspection needs to be conducted to ensure the                      compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	burnsa	08/17/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403139635	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5832633">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5832633</a>
699105983	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5832629">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5832629</a>