

Inspection Photos and Issue Report

8/25/2022

Operator: LOCIN OIL CORPORATION - 51130

Location #322320

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322320



August 25, 2022



August 25, 2022

Photo 1: Photos 1-2 provide an overview of the Location from north, northeast, southeast to south. Photos also show Undesirable Plant Species established on the Location- weed management required.

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322320



August 25, 2022



August 25, 2022

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322320



Photo 3: Photo example showing weed establishment on the Location.

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322320



Photo 4: Photo example showing weed establishment on access road.

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322320



Photo 5: Signage at well head shows Foundation Energy Management. Records shows Locin Oil Corp as Operator, effective 3/1/2022 .

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322320



Photo 6: Continue from photo 5. Photo show fluids within the secondary containment of the methanol tank.

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322320



Photo 7: Photo example showing signage at battery posted as Foundation Energy Management. Records shows Locin Oil Corp as Operator, effective 3/1/2022. Labels on tanks also missing required information per 605.h.

Inspection Photos

LOCIN OIL CORPORATION - 51130

Location #322320



August 25, 2022



August 25, 2022

Photo 8: Photo taken from the access road. Photo shows erosion control and stabilization BMPs are missing or insufficient along entire access road- erosion degradation and sediment transport evident.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322320



Photo 9: Photo taken from the access road between Utah Gas Corp's Federal-Carbonera 1-2, and Locin's Government 1 Location; access road is shared between the two Operators. Photo shows erosion control and stabilization BMPs are missing or insufficient along entire access road- erosion degradation and sediment transport evident.

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322320



Photo 10: Photo taken from the access road south of Utah Gas Corp's Federal-Carbonera 1-2; access road is shared between the two Operators. Photo shows erosion control and stabilization BMPs are missing or insufficient along entire access road- erosion degradation and sediment transport evident.

Inspection Photos
Operator Name: LOCIN OIL CORPORATION - 51130
Location #322320



Photo 11: Continued from photo 10. Hard hat in photo for scale/reference.