

Inspection Photos

Loc: 307032

Operator: SIMCOE LLC

Inspection Date: 8/30/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 307032 | Date: 8/30/2022

Inspection Photos



Photo 1. Facing west along the access road. The road has been washed out in this area and will need to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 307032 | Date: 8/30/2022

Inspection Photos



Photo 2. Facing back east along the access road. The road has been washed out in this area and will need to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 307032 | Date: 8/30/2022

Inspection Photos



Photo 3. Facing west toward the location which is fenced. The gate is left open and should remain closed to prevent livestock entry.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 307032 | Date: 8/30/2022

Inspection Photos



Photo 4. The fill slope of the location has sparse vegetation and looks to be heavily grazed down. The gate to the location should remain closed and additional seeding is needed in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 307032 | Date: 8/30/2022

Inspection Photos



Photo 5. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 307032 | Date: 8/30/2022