

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/25/2022

Submitted Date:

08/31/2022

Document Number:

697601866

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Ahmadian, Alexander On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
, KPK		cogcc@kpk.com	All Inspections
Cuthbertson, Scott		scott.cuthbertson@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
-, Marcom		primarycontractor@marcomllc.net	

General Comment:

Environmental inspection of Spill ID 482755 reported by Operator 8/13/2022 for the spill of oil, produced water, and condensate from the Rodgers #1 Flowline.
Previous Environmental Inspections conducted 8/15/2022, 8/17/2022, and 8/22/2022.
At the time of inspection, crews were on site and were repairing the flowline at the westernmost excavation. A total of two excavations and two hydrovac potholes were present on location; two excavations open for flowline repair and a hydrovac pothole conducted as spill response to expose the flowline at the spill location.

Location

Overall Good:

Emergency Contact Number:

Comment: Warning signage has been installed on the fencing of the excavations. However, no emergency phone number is visible anywhere on the signage.

Corrective Action: Install warning signage with Rule 913.b.(5).B.i and COGCC Guidance 913.b.(5)B i-v

Date: 09/01/2022

Overall Good:

Spills:					
Type	Area	Volume			

In Containment: Yes

Comment:

Multiple Spills and Releases?

Fencing/:					
Type	OTHER				
Comment:	Operator has installed both cattle panel fencing surrounding the orange construction fencing around the impacted hydrovac potholes.				
Corrective Action:					Date:

Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:

Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Environmental

Spill/Remediation:

Comment: Little progress has been made on the spill remediation. Obvious impacts remain visible in-situ. Hydrocarbon odors present outside of fencing.

Corrective Action: As per Rule 912.b.(2), Operators will investigate, clean up, and document impacts resulting from Spills and Releases as soon as the impacts are discovered.

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697601867	Photo Documentation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5848908