

Colorado Oil and Gas Conservation Commission

Mustang V41-27-28XRLNB Issue Report




Created on July 22, 2022

Captured on July 21, 2022



Type	Count
Observation	1

No.	Type	Severity	Created	Status	Cost of Repair
18	 Observation	—	July 22, 2022	Open	—
					Total: \$0.00

18 - Observation

Open

Jul 21, 2022 at 11:27am



Details

Summary: Bird protector on ECD appears to be gone and needs replaced. All stacks, vents, or other openings will be equipped with screens or other appropriate equipment to prevent entry by wildlife, including birds and bats. With a corrective action date of 7/29/22

Created:	Jul 22, 2022, 11:21am by Adam Burns
Cost of Repair:	—
Coordinates:	40.28622, -104.41439