

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/08/2022

Submitted Date:

09/13/2022

Document Number:

697601880

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Ahmadian, Alexander On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
, KPK		cogcc@kpk.com	All Inspections
Gorka, Ray		RGorka@kpk.com	KPK environmental
-, Marcom		primarycontractor@marcomllc.net	
Meis, Craig		cmeis@kpk.com	

General Comment:

This is an environmental inspection for Spill ID 478542 Cosslet A 9 Flowline. Any corrective actions from previous inspections that have not been addressed are still applicable.
There were no operator or contract environmental personnel on location at the time of this field inspection.
Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type: WEEDS

Comment:

Corrective Action:

Date: 09/22/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type

Comment:

Corrective Action:

Date: _____

Venting:

Yes/No

Comment:

Corrective Action:

Date: _____

Flaring:

Type

Comment:

Corrective Action:

Date: _____

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil				
Comment	Contaminated soil has been completely removed for the site.			
Corrective Action				Date:

Spill/Remediation:

Comment:	Spill excavation remains open and impacts remain in-situ. Free product is pooling quickly within the excavation.		
Corrective Action:	In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered.	Date:	11/10/2020

Emission Control Burner (ECB):	_____
Comment:	_____
Pilot:	_____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697601881	Photo Documentation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5858748