

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/08/2022

Submitted Date:

09/09/2022

Document Number:

690203391

**FIELD INSPECTION FORM**Loc ID 308667 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
dbaca@ogrisop.com		dbaca@ogrisop.com	
WARD, GIENA		gward@ogrisop.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278288	WELL	PR	07/01/2011	GW	071-08419	GOLDEN EAGLE 34-5	RI

**General Comment:**

This is a stormwater management inspection.  
See attached photos and additional details within this report.

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is erosion occurring along the road at the compressor facility. Stormwater is not being diverted to the diversion ditches which is creating erosion chanel along the road. There is also erosion along the road side that will need BMP's to slow stormwater and prevent further erosion.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 10/10/2022

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403160792	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5852246">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5852246</a>
690203392	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5852222">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5852222</a>