

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/08/2022

Submitted Date:

09/13/2022

Document Number:

697601884

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Ahmadian, Alexander On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
-, Marcom		primarycontractor@marcomllc.net	
Gorka, Ray		RGorka@kpk.com	KPK environmental
Meis, Craig		cmeis@kpk.com	
Graber, Nikki		nikki.graber@state.co.us	
, KPK		cogcc@kpk.com	All Inspections
MacLaren, Joe		joe.maclaren@state.co.us	

General Comment:

This is an environmental inspection for Spill ID 467173. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment: None present.

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type

Comment: Cattle guard fencing around excavation is in good condition.

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil				
Comment	Contaminated stockpile has been completely removed from the site.			
Corrective Action			Date:	

Spill/Remediation:

Comment:	Spill excavation (approximate size 24'x12'x8') remains open and impacts remain in-situ. Free product is pooling quickly within the excavation.		
Corrective Action:	In accordance with 913.d.(1) Operator will investigate impacts to soil, groundwater, and surface water as soon as the impacts are discovered.	Date:	09/14/2022

Emission Control Burner (ECB):	_____
Comment:	_____
Pilot:	_____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
Spill excavation is in close proximity to livestock and occupied housing and other structures. Free product is pooling within the excavation and the hydrocarbon odor is strong.	ahmadiaa	09/13/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403165097	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5859311
697601885	Photo Documentation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5859305