

HALLIBURTON

iCem® Service

CONFLUENCE DJ LLC-EBUS

Canal 22-1-3L

Production Casing

Job Date: Thursday, September 09, 2021

Sincerely,

Mike Loughran

Legal Notice

Disclaimer:

All information in this report is provided subject to the terms and conditions which govern the services provided by Halliburton. Halliburton personnel use their best efforts in gathering information and their best judgment in interpreting it, but any interpretation, research, analysis or recommendation furnished by Halliburton are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and empirical relationships and assumptions are not infallible, and with respect to which professionals in the industry may differ. iCem 3D Displacement results are used to understand how fluids intermix during a cement job. Simulation and 3D displacement results are not intended as and should not be used as a replacement for bond logs in determining top of cement. Current 3D model calculations are known to model more volume than the input volume for standard cases due to known calculation improvements required. For rotational cases, the modeled volume will be impacted by the same calculations impacting the standard cases, as well as additional constraints imposed to make the calculation time required operationally feasible. Therefore, until further notice, 3D displacement results should not be used for replacement of a bond log, or used as an identifier of top of cement. HALLIBURTON IS UNABLE TO GUARANTEE THE ACCURACY OF ANY CHART INTERPRETATION, RESEARCH ANALYSIS, OR JOB RECOMMENDATION and any interpretation or recommendation is not for use of or reliance upon by any third party. The customer has full responsibility for any of its decisions which are based on the information provided in this report.

Table of Contents

1.0 Cementing Job Summary4

 1.1 Executive Summary 4

2.0 Real-Time Job Summary7

 2.1 Job Event Log 7

3.0 Attachments.....9

 3.1 Job Chart..... 9

1.0 Cementing Job Summary

1.1 Executive Summary

Halliburton appreciates the opportunity to perform the cementing services on the Canal 22-1-3L production casing. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

Approximately 30 bbl. of spacer were returned to surface.

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

Halliburton Fort Lupton

The Road to Excellence Starts with Safety

Sold To #: 375989		Ship To #: 9082340		Quote #:		Sales Order #: 0907367976				
Customer: CONFLUENCE DJ LLC-EBUS				Customer Rep: Gary Doke						
Well Name: CANAL			Well #: 22-1-3L			API/UWI #:				
Field:		City (SAP): HUDSON		County/Parish: WELD			State: COLORADO			
Legal Description:										
Contractor: ENSIGN DRLG				Rig/Platform Name/Num: ENSIGN 161						
Job BOM: 7523										
Well Type: HORIZONTAL OIL										
Sales Person: HALAMERICA\HB41307				Srv Supervisor: Michael Loughran						
Job										
Job depth MD		18197ft		Job Depth TVD						
Well Data										
Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft
Casing		9.625	8.921	36			0	2701		
Casing		5.5	4.778	20		P-110	0	18197		
Open Hole Section			8.5				2650	18208		
Tools and Accessories										
Type	Size in	Qty	Make	Depth ft		Type	Size in	Qty	Make	
Float Shoe	5.5			18197		Top Plug	5.5	1		
Float Collar	5.5			18149		Bottom Plug	5.5	2	HES	
						Plug Container	5.5	1	HES	
						Centralizers	5.5	330	HES	

Fluid Data									
Stage #: 1									
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
1	Spacer	Tuned Prime Cement Spacer	190	bbl	12	3.26		6	6544
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
2	Cement	ElastiCem™ Cement	2120	sack	14.4	1.7	7.26	8	15391
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
3	Displacement	Fresh Water with MMCR	30	bbl	8.34			9	1260
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
4	Displacement	Treated Fresh Water	369	bbl	8.34			8	15498
Cement Left In Pipe		Amount	47.63 ft		Reason			Shoe Joint	
Mix Water:		pH 6	Mix Water Chloride:		LESS 200 ppm		Mix Water Temperature:		76°F
Plug Bumped?		Yes	Plug Displaced by:		8.33 lb/gal Treated Water		Disp. Temperature:		76°F
Cement Returns:		0 bbl.	Bump Pressure:		2931 PSI		Floats Held?		Yes
Comment: PUMPED 190 BBL. TUNED PRIME SPACER 12 PPG AND 2120 SACKS OR 641.87 BBL. 14.4 PPG ELASTICEM. FINAL CIRCULATING PRESSURE OF 2931 PSI AT 4 BPM. BUMP PLUG AND BROUGHT PRESSURE TO 3500 PSI. RELEASE PRESSURE, FLOATS HOLD. 5 BBL. BACK TO PUMP TRUCK. APPROX 30 BBL. SPACER TO SURFACE. ESTIMATED TOC=3400'.									

2.0 Real-Time Job Summary

2.1 Job Event Log

Seq. No.	Activity	Date	Time	Dwnhole Density (ppg)	Cmb Pump Rate (gpm)	Pump A Pressure (psi)	Cmb Stg Total (bbl)	Comments
1	Check Floats	9/8/2021	12:00:00					CREW CALLED OUT AT 1200 hrs. 9/8/2021. Requested on location 1800 hrs. 9/8/2021
2	Pre-Convoy Safety Meeting	9/8/2021	17:15:00					CREW DISCUSSED ROUTES, HAZARDS, AND COMMUNICATION WITH CREW.
3	Crew Leave Yard	9/8/2021	17:30:00					Crew leaves yard
4	Arrive At Loc	9/8/2021	18:00:00					MEET WITH CO. MAN TO DISCUSS JOB; SURFACE CASING- 9.625" 36 LB/FT @ 2701", 5.5" CASING: 20 LB/FT P-110 TOTAL 18196.85', 8.5" HOLE, TD 18208", F/C 18149.22, TVD- 7300". PUMP FRESH WATER DISPLACEMENT. Water test 76 degrees, PH 6, Chlorides less 200 ppm
5	Pre-Rig Up Safety Meeting	9/8/2021	18:10:00					HAZARD HUNT. DISCUSSED POSSIBLE HAZARDS ASSOCIATED WITH LOCATION, RIG UP, AND WEATHER.
6	Rig-Up Equipment	9/8/2021	18:20:00					CREW STAGED EQUIPMENT AND RIGGED UP BULK, IRON AND WATER HOSES TO PERFORM JOB.
7	Pre-Job Safety Meeting	9/8/2021	20:00:00	8.27	0.0	4.03	0.00	SAFETY MEETING WITH HALLIBURTON, AND RIG PERSONNEL. CREW COMMUNICATED POTENTIAL SAFETY HAZARDS, AND JOB DETAILS.
8	Start Job	9/8/2021	20:27:26	8.28	0.0	9.16	11.85	Begin recording data. RIG CIRCULATES 13 BPM/1700 PSI, Rig pumps 50 bbl. D822
9	Pressure Test	9/8/2021	20:55:30	8.37	4.2	1225.97	1.97	PRESSURE TEST HES LINES 5000 PSI
10	Drop Bottom Plug	9/8/2021	21:00:18	8.29	0.0	12.11	1.98	BOTTOM PLUG VERIFIED BY GARY/JOHNNY
11	Pump Spacer 1	9/8/2021	21:00:58	8.30	0.0	11.37	0.00	190 BBLS TUNED PRIME SPACER 12 PPG, 3.26 YIELD, 20.12 GAL/SACK. D-AIR ON FLY
12	Shutdown	9/8/2021	21:33:58	11.45	35.0	34.50	191.28	SHUTDOWN
13	Drop Bottom Plug	9/8/2021	21:41:19	0.08	0.0	8.35	192.23	BOTTOM PLUG VERIFIED BY GARY/JOHNNY
14	Pump Tail Cement	9/8/2021	21:41:27	0.08	0.0	8.57	0.00	2120 SACKS SBM CEM, 641.87 BBLS. 14.4 PPG, 1.7 YIELD, 7.26 GAL/SACK. USED 110 GALLONS D-AIR TOTAL JOB
15	Shutdown	9/8/2021	23:05:30	0.29	0.0	74.85	647.01	SHUTDOWN/WASH PUMPS AND LINES

16	Drop Top Plug	9/8/2021	23:19:38	8.16	0.0	7.88	0.00	TOP PLUG VERIFIED BY GARY/JOHNNY
17	Pump Displacement	9/8/2021	23:20:51	8.17	0.0	1.73	0.00	399 BBLS BY STRAP. FRESH WATER DISPLACEMENT. FIRST 30 BBLS HAS 15 GALLONS MICRO MATRIX RETARDER. 10 GALLONS CLA-WEB AND 3 LBS BE-3 THROUGHOUT. SEE SPACER AT 370 BBLS INTO DISPLACEMENT. APPROX 30 BBLS SPACER TO SURFACE. ESTIMATED TOC=3400'
18	Bump Plug	9/9/2021	00:17:32	8.40	0.0	3342.61	0.00	FCP 2931 PSI/4 BPM. BUMP PRESSURE 3500 PSI
19	Check Floats	9/9/2021	00:22:00	8.26	0.0	1493.23	0.00	RELEASE PRESSURE, FLOATS HOLD. 5 BBL BACK TO PUMP TRUCK.
20	End Job	9/9/2021	00:22:51	8.14	0.0	18.94	0.00	STOP RECORDING DATA. HES FLUSHES STACK WITH 40 BBLS WATER
21	Pre-Rig Down Safety Meeting	9/9/2021	00:45:00					DISCUSSED POSSIBLE HAZARDS ASSOCIATED WITH WEATHER, LOCATION AND RIGGING DOWN IRON AND HOSES.
22	Rig-Down Equipment	9/9/2021	00:50:00					RIG DOWN BULK AND MIXING EQUIPMENT
23	Rig-Down Completed	9/9/2021	02:00:00					ALL HALLIBURTON ITEMS WERE STOWED FOR TRAVEL, AND LOCATION WAS CLEAN.
24	Crew Leave Location	9/9/2021	03:00:00					THANK YOU FOR USING HALLIBURTON – MIKE LOUGHRAN AND CREW.

3.0 Attachments

3.1 Job Chart

