

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403173425

Date Received:  
09/21/2022

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
-		<a href="mailto:RangelyRegulatr@scoutep.com">RangelyRegulatr@scoutep.com</a>
<a href="#">Patterson, Chris</a>		<a href="mailto:Chris.Patterson@scoutep.com">Chris.Patterson@scoutep.com</a>
<a href="#">Sanford, Anita</a>		<a href="mailto:Anita.Sanford@scoutep.com">Anita.Sanford@scoutep.com</a>

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 696204090

Inspection Date: 09/12/2022

FIR Submit Date: 09/14/2022

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

**LOCATION - Location ID: 314661**

Location Name: LARSON, F V-62N102W Number: 36SEnw County: \_\_\_\_\_

Qtrqr: SEnw Sec: 36 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.101380 Longitude: -108.793880

**FACILITY - API Number: 05-103-00 Facility ID: 314661**

Facility Name: LARSON, F V-62N102W Number: 36SEnw

Qtrqr: SEnw Sec: 36 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.101380 Longitude: -108.793880

**CORRECTIVE ACTIONS:**

**1** CA# 164565

Corrective Action: Comply with Rules 1004.e and 606.c

Date: 09/21/2022

Response: CA COMPLETED

Date of Completion: 09/21/2022

Operator Comment: Weed removed and will be re-sprayed in the spring

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 164566

Corrective Action: Comply with 1004 rules and conduct additional reclamation; ensure BMPs are implemented to stabilize the seeded soils and to prevent weed establishment.

Date: 11/15/2022

Response: CA COMPLETED

Date of Completion: 09/21/2022

Operator Comment: Installed additional BMP's and seeded the area

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**3** CA# 164567

Corrective Action: Comply with Rule 1002.f; install and maintain stormwater and erosion control measures; if it is determined that a specific BMP is insufficient to mitigate degradation on a site, cannot be implemented per installation specification, or maintained in effective operating condition, then alternative BMPs that are better suited to meet the site's conditions should be considered and applied, or used in conjunction. Upon completion of additional reclamation efforts, ensure BMPs are implemented to stabilize the seeded soils and to prevent weed establishment.

Date: 09/21/2022

Response: CA COMPLETED

Date of Completion: 09/21/2022

Operator Comment: Installed addition BMP's and erosion control measures.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Please see attached PICs

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Patterson

Signed: \_\_\_\_\_

Title: Sr. HSE Coordinator

Date: 9/21/2022 2:28:57 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403173441	PIC
403173444	PIC
403173447	PIC

Total Attach: 3 Files