

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403180049

Date Received:  
09/28/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
Romana Cowden	720-951-5895	cogcc.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204038

Inspection Date: 08/30/2022

FIR Submit Date: 09/02/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 416157

Location Name: Puckett Number: 697-26A County: \_\_\_\_\_

Qtrqr: NWNE Sec: 26 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.498914 Longitude: -108.183089

FACILITY - API Number: 05-045-00 Facility ID: 416157

Facility Name: Puckett Number: 697-26A

Qtrqr: NWNE Sec: 26 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.498914 Longitude: -108.183089

CORRECTIVE ACTIONS:

1 CA# 164297

Corrective Action: Conduct reclamation on both the interim areas, and off-site areas east of the Location disturbed due to stormwater runoff from the Location; comply with 1002.f and implement BMPs to stabilize reclaimed areas.

Date: 10/02/2022

Response: CA COMPLETED

Date of Completion: 09/20/2022

Operator Comment: Repaired. See attached photos.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

2 CA# 164298

Corrective Action: Comply with Rule 606 and remove debris.

Date: 09/09/2022

Response: CA COMPLETED

Date of Completion: 09/20/2022

Operator Comment: Erosion was repaired. Debris were removed. Additional BMPS, such as rock armor and seeding, were installed. See attached photos

COGCC Decision:

COGCC  
Representative:

3 CA# 164299

Corrective Action: Comply with Rule 1002.f; install or repair stormwater and erosion control BMPs in accordance with good engineering practices; ensure BMPs are maintained in proper functioning condition until Location receives a passing final reclamation inspection.

Date: 09/09/2022

Response: CA COMPLETED

Date of Completion: 09/20/2022

Operator Comment: Repaired. See attached photos.

COGCC Decision:

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed:

Title: EHS

Date: 9/28/2022 6:16:54 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403180053	Example of additional BMPS installed on location (sed trap armored)
403180055	Example of additional BMPS installed on location (rock armoring)
403180063	Erosion on road repaired. Berm repaired and seeded.

Total Attach: 3 Files