

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403172017

Date Received:
09/20/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Patterson, Chris</u>		<u>Chris.Patterson@scoutep.com</u>
.		<u>RangelyRegulatr@scoutep.com</u>
<u>Sanford, Anita</u>		<u>Anita.Sanford@scoutep.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204063

Inspection Date: 09/12/2022

FIR Submit Date: 09/13/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 314658

Location Name: LARSON, F V-62N102W Number: 35SENE County: _____

Qtrqtr: SENE Sec: 35 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.101410 Longitude: -108.803550

FACILITY - API Number: 05-103-00 Facility ID: 314658

Facility Name: LARSON, F V-62N102W Number: 35SENE

Qtrqtr: SENE Sec: 35 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.101410 Longitude: -108.803550

CORRECTIVE ACTIONS:

1 CA# 164517

Corrective Action: Comply with Rules 1004.e and 606.c. Continue to monitor and manage weeds until Location receives a passing final reclamation inspection.

Date: 09/20/2022

Response: CA COMPLETED

Date of Completion: 09/20/2022

Operator Comment: Weeds removed- will be sprayed again in the spring

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

3 CA# 164519

Corrective Action: Comply with Rule 1002.f; install and maintain stormwater and erosion control measures; if it is determined that a specific BMP is insufficient to mitigate degradation on a site, cannot be implemented per installation specification, or maintained in effective operating condition, then alternative BMPs that are better suited to meet the site's conditions should be considered and applied, or used in conjunction. Upon completion of additional reclamation efforts, ensure BMPs are implemented to stabilize the seeded soils and to prevent weed establishment.
Continue to monitor and manage stormwater until Location receives a passing final reclamation inspection.

Date: 09/20/2022

Response: CA COMPLETED

Date of Completion: 09/20/2022

Operator Comment: Have installed addition BMP's and seed mats.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: Please see attached PICS

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Patterson

Signed: _____

Title: Sr. HSE Coordinator

Date: 9/20/2022 3:10:11 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403172017	FIR RESOLUTION SUBMITTED
403172067	PIC
403172070	PIC

Total Attach: 3 Files