

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403172108

Date Received:  
09/20/2022

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Sanford, Anita</u>		<u>Anita.Sanford@scoutep.com</u>
<u>Patterson, Chris</u>		<u>Chris.Patterson@scoutep.com</u>
		<u>RangelyRegulatr@scoutep.com</u>

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 696204073

Inspection Date: 09/12/2022

FIR Submit Date: 09/13/2022

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

**LOCATION - Location ID: 314707**

Location Name: F V LARSON B-62N102W Number: 26SESE County: \_\_\_\_\_

Qtrqtr: SESE Sec: 26 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.110390 Longitude: -108.805620

**FACILITY - API Number: 05-103-00 Facility ID: 314707**

Facility Name: F V LARSON B-62N102W Number: 26SESE

Qtrqtr: SESE Sec: 26 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.110390 Longitude: -108.805620

**CORRECTIVE ACTIONS:**

1  CA# 164528

Corrective Action: Comply with Rules 1004.e and 606.c. Continue to monitor and manage weeds until Location receives a passing final reclamation inspection.

Date: 09/20/2022

Response: CA COMPLETED

Date of Completion: 09/20/2022

Operator Comment: Weeds removed and will be spayed in the spring

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

3  CA# 164530

Corrective Action: Comply with Rule 1002.f; install and maintain stormwater and erosion control measures; if it is determined that a specific BMP is insufficient to mitigate degradation on a site, cannot be implemented per installation specification, or maintained in effective operating condition, then alternative BMPs that are better suited to meet the site's conditions should be considered and applied, or used in conjunction. Upon completion of additional reclamation efforts, ensure BMPs are implemented to stabilize the seeded soils and to prevent weed establishment.

Continue to monitor and manage stormwater until Location receives a passing final reclamation inspection.

Date: 09/20/2022

Response: CA COMPLETED

Date of Completion: 09/20/2022

Operator Comment: Addition BMPs installed

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Please see attached PICs

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Patterson

Signed: \_\_\_\_\_

Title: Sr HSE Coordinator

Date: 9/20/2022 3:48:52 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403172108	FIR RESOLUTION SUBMITTED
403172200	PIC
403172201	PIC

Total Attach: 3 Files