

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403187700

Date Received:

10/05/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>BACA DAVID</u>	<u>719-859-4066</u>	<u>dbaca@ogrisop.com</u>
<u>ATWATER, BONNIE</u>	<u>432-755-0212</u>	<u>batwater@ogrisop.com</u>
<u>WARD, GIENA</u>	<u>719-220-4041</u>	<u>gward@ogrisop.com</u>
<u>O'SHIELDS, CHARLIE</u>	<u>940-682-5030</u>	<u>coshields@ogrisop.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690203380

Inspection Date: 09/08/2022

FIR Submit Date: 09/09/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: OGRIS OPERATING LLC

Company Number: 10758

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

LOCATION - Location ID: 307298

Location Name: APACHE CANYON-634S68W Number: 9SWNE County: LAS ANIMAS

Qtrqtr: SWNE Sec: 9 Twp: 34S Range: 68W Meridian: 6

Latitude: 37.101220 Longitude: -104.998170

FACILITY - API Number: 05-071-00 Facility ID: 217413

Facility Name: APACHE CANYON Number: 9-7

Qtrqtr: SWNE Sec: 9 Twp: 34S Range: 68W Meridian: 6

Latitude: 37.101220 Longitude: -104.998170

CORRECTIVE ACTIONS:

1 ☒ CA# 164436

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 09/10/2022

Response: CA COMPLETED

Date of Completion: 09/10/2022

Operator Comment: THE LEAKING PACKING BOLT HAS BEEN TIGHTENED AND MAINTENANCE HAS BEEN PERFORMED TO ENSURE ALL VALVES, PIPES, FITTINGS ARE SECURELY FASTENED. All production equipment are in good mechanical condition.

COGCC Decision: Approved

COGCC Representative:

2 ☒ CA# 164437

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 10/09/2022

Response: CA COMPLETED

Date of Completion: 09/30/2022

Operator Comment: The well pad has been bladed and groomed to eliminate the vehicle rutting. DIVERSION DITCHES ALONG THE ACCESS LEADING TO THE LOCATION HAVE BEEN REDEFINED TO BETTER DIRECT STORMWATER OFF OF LOCATION.

COGCC Decision: Approved

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN COMPLETED. SEE PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA WARD

Signed:

Title: SR. ENVIRONMENTAL

Date: 10/5/2022 9:27:48 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403187700	FIR RESOLUTION SUBMITTED
403187718	PHOTO LOG

Total Attach: 2 Files