

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/04/2022

Submitted Date:

10/05/2022

Document Number:

700704592

FIELD INSPECTION FORM

Loc ID: 316580 Inspector Name: Ramsey, Scott On-Site Inspection: 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

4 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10384

Name of Operator: GENESIS GAS & OIL COLORADO LLC

Address: 2441 NACOGDOCHES RD PMB 701

City: SAN ANTONIO State: TX Zip: 78217

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Jeffrey Karcz	(303) 909-6401	jkarcz@genesigoco.com	
, Genesis	210-363-2859	mkimmel@genesigoco.com	
, COGCC		conor.pesicka@state.co.us	
, COGCC		dnr_cogccengineering@state.co.us	engineering

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286505	WELL	AC	11/11/2008	OBW	103-10894	FLETCHER GULCH 3-21	TA

General Comment:

COGCC Inspection Report Summary
 On Tuesday 10/4/2022 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at Genesis Fletcher Gulch 3-21, at Location # 316580 in Rio Blanco county Colorado.
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.
 While there, I observed well is not producing. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management.
 During this inspection the following possible compliance issues were observed:
 1. Location covered with weeds.
 2. Well head signage is lacking information.
 3. No emergency number posted.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Entrance		
Corrective Action:	Provide proper information on signage		Date: 11/16/2022
Emergency Contact Number:			
Comment:	No emergency number posted.		
Corrective Action:	Provide proper information on signage		Date: 11/16/2022
Good Housekeeping:			
Type	WEEDS		
Comment:	Location is covered in weeds		
Corrective Action:	Remove weeds		Date: 10/14/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Other	# 1		corrective date
Comment:	Well head		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 286505 Type: WELL API Number: 103-10894 Status: AC Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last Mit done 6/30/2015
 Well was found in state of Temporary Abandonment.

 Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b.

Corrective Action: **Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210.** Date: 11/16/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700704599	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5880089