



**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Adequate	Date:	
Corrective Action:			

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused Equipment in multiple locations needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	10/20/2022
Type	OTHER		
Comment:	Stained Soil in multiple spots needs to be removed. See attached photos.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	10/20/2022

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Other	#		corrective date
Comment:	Mechanical conditions appears to be on balon valve needs repaired or replaced on the North Platte K-31-O34-28HNB. See attached photo.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 10/20/2022

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 332135 Type: LOCATION API Number: - Status: AC Insp. Status: AC

**Producing Well**

Comment: AC

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On Monday 10/10/22 at approximately 0945hrs, I, Inspector Adam Burns, Conducted an on-site inspection at North Platte 41-28 Pad of Civitas, at Location ID: 332135 in Weld County, Colorado.                      During this inspection the following possible compliance issues were observed:                      Unused Equipment in multiple locations needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 10/20/22.                      Stained Soil in multiple spots needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 10/20/22.                      Mechanical conditions appears to be on balon valve needs repaired or replaced on the North Platte K-31-O34-28HNB. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a corrective action date of 10/20/22.                      See attached photo.                      Submit pictures on FIRR.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	burnsa	10/11/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699106155	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883245">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5883245</a>