


INSPECTOR COMMENT: Sign not posted or information inaccurate at battery no volume sign and NFPA placards are faded

**CA 1): Install sign to comply with Rule 605.d. by 11/11/22**

Operator immediately replaced faded placards with new placards and identified tank contents and tank volume capacity by end of day on 10/11/22.



INSPECTOR COMMENT: mechanical issue Well head leaking around tubing

**CA 2: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. by end of day 10/12/22**

Operator was contacted by phone to remedy mechanical issue within 24 hrs. Operator responded immediately and tightened all valves pipes and fittings and hammered wellhead tight. Re-inspected with soapy water and confirmed repair.



CONTINUED , RESPONSE .....

FIR Doc #707900052, Loc ID: 322234 Name: RAINBOW 27-20; API #05-043-06150

INSPECTOR ALSO COMMENTED that valves on back of oil tank could not be left open-ended and needed to be plugged. Did not issue a corrective action.

Operator nipped up fittings that had been disconnected for tank drainage and made sure no open-ended valves were left.

