

Inspection Photos and Issue Report

10/17/2022

Operator: LARAMIE ENERGY LLC - 10433

Location #427315

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location #427315



Photo 1: Photos 1-2 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east. Photos also show areas not needed for production have been reduced per 1003 requirements and CAs.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location #427315



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location #427315



Photo 3: Photo taken from the southeast end of the Location. Photo shows stormwater discharge point from the Location has not been constructed with a properly engineered outlet per good engineering practices, or maintained in a proper functioning condition, resulting in erosion and degradation. Photo right shows stormwater is being diverted around the wattle control, resulting in degradation.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location #427315



Photo 4: Continued from photo 3. Photos taken from the slopes southeast of the Location. Photos show discharge point has not been constructed with a properly engineered outlet, resulting in erosion and degradation to the slopes south of the Location

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location #427315



Photo 5: Photo taken from the southeast end of the Location. Photo shows areas that do not appear to be progressing towards 1003 standards; livestock use is evident within these areas and may be hindering reclamation.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location #427315



Photo 6: Photos taken from the west end of the Location. Photos show areas are bare and exposed, and not progressing towards 1003 revegetation standards. Stormwater and erosion control BMPs are also missing or insufficient, resulting in erosion and degradation due to runoff. Additional stormwater management and reclamation required.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location #427315



October 17, 2022



October 17, 2022

Photo 7: See comments under photo 6.