

**COGCC 6/16/2022 Follow up Inter Rec Inspection Notices Received**

**Oxnard East Pad – Facility ID 452516 – Status: PR**

**Fir Doc #: 697504028**

**Follow up to field Inspection Report Doc#  
697503532**

Number of Corrective Actions: 1

DUE DATE for corrective actions: [11/21/2022](#)

**Corrective Action 1** – Comply with Rule 1003. Operator shall redo the revegetation in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use the approved seed mixture provided by the surface owner. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management. Native seed mix should only be planted to a depth of ¼ to ½ an inch

The corrective action was completed on 10/29/2022 by CB Services. Re seeding was done in accordance with the approved seed mixture by the landowner.

PHOTOS

**Inspection Photos**  
**Location Name: Oxnard East /0607-8CH**  
**Location ID: 452516**



**Photo 1.** Photo taken from the southeastern interim reclamation area, facing East. Photo illustrates Operator has responded to the previous corrective action to perform additional interim reclamation activities; however, there was little to no germination throughout the interim reclamation area.



**Photo 2.** Photo taken from the southeastern interim reclamation area, facing North. See comments under Photo 1.



**Photo 3.** Photo taken from the eastern interim reclamation area, facing North. See comments under Photo 1.

Note: the Kochia seedlings are coming up in the drill rows, which is not desirable vegetation.



**Photo 4.** Photo taken from the interim reclamation area. Photo illustrates that one of the desirable grass species was planted deeper than 1.5 inches. Native seeds should not be planted that deep and maybe why this attempt failed.



**Photo 5.** Photo taken from the northeastern interim reclamation area, facing North. See comments under Photo 1.



**Photo 6.** Photo taken from the northeastern interim reclamation area, facing West. See comments under Photo 1.

Pictures of the corrective action being completed on 10/29/2022:



