

## Albidrez, Patricia [RigUp]

---

**From:** Jacobs, Jess [Bedrock Petroleum Consultants]  
**Sent:** Thursday, July 14, 2022 10:29 AM  
**To:** McFarland - DNR, Nick  
**Cc:** RBUARORegulatory; Schneider, Jeremie; Albidrez, Patricia [RigUp]  
**Subject:** CVX Procedure Modification: THOMPSON C33-69HN (33589)

Hey, Nick.

Just an FYI. Working on this Thompson C33-69HN and about to finish it up. We shot holes in the 7" csg at 200ft to try and balance a plug to surface. We were unable to get circulation. We are going to attempt to shoot holes at 100ft and see if we can circulate there and balance cement to surface. If we cannot, we will TIH and pump cmt inside 7" csg from 200ft to surface. Again, just an FYI here on the slight change at surface. Thanks, Nick. Have a good one.

Jess E. Jacobs  
970-744-1168

