

## Zimmerman/Chamberlin

API 05-081-06668

Response to Field Insp 700704624 from Scott Ramsey/COGCC  
dated 10/21/2022



ROBERT L BAYLESS  
PRODUCER LLC

### Signs/Marker:

- Propane Tank missing information.

BEFORE



Unmarked propane? tank

AFTER



### Good Housekeeping:

- Random debris



Debris/ unmarked can





# Zimmerman/Chamberlin

API 05-081-06668

Response to Field Insp 700704624 from Scott Ramsey/COGCC  
dated 10/21/2022



ROBERT L BAYLESS  
PRODUCER LLC

## BEFORE

- Random debris (cont)



Debris/storage of equipment



Debris



Debris

## AFTER





## Zimmerman/Chamberlin

API 05-081-06668

Response to Field Insp 700704624 from Scott Ramsey/COGCC  
dated 10/21/2022



ROBERT L BAYLESS  
PRODUCER LLC

### BEFORE

- Random debris (cont)



Debris/storage of equipment



Debris/storage of equipment



Debris/storage of equipment

### AFTER



Removed debris (no photo)



## Zimmerman/Chamberlin

API 05-081-06668

Response to Field Insp 700704624 from Scott Ramsey/COGCC  
dated 10/21/2022



ROBERT L BAYLESS  
PRODUCER LLC

### BEFORE

- Random staining



### AFTER



- Storage of Supl



LANDOWNER has moved all personal  
property away from equipment. (no  
photos)

### Storage of equipment next to production equipment





## Zimmerman/Chamberlin

API 05-081-06668

Response to Field Insp 700704624 from Scott Ramsey/COGCC  
dated 10/21/2022



ROBERT L BAYLESS  
PRODUCER LLC

### BEFORE

- Storage of Supl (cont)



Storage of equipment next to production equipment



Storage of equipment next to production equipment

### AFTER

LANDOWNER has moved all personal property  
away from equipment. (no photos)



## Zimmerman/Chamberlin

API 05-081-06668

Response to Field Insp 700704624 from Scott Ramsey/COGCC  
dated 10/21/2022



ROBERT L BAYLESS  
PRODUCER LLC

### BEFORE

- Storage of Supl (cont)



Storage of equipment next to production equipment



### AFTER

LANDOWNER has moved all personal property  
away from equipment. (no photos)





## Zimmerman/Chamberlin

API 05-081-06668

Response to Field Insp 700704624 from Scott Ramsey/COGCC  
dated 10/21/2022

- Storage of Supl (cont)



ROBERT L BAYLESS  
PRODUCER LLC



Bayless has been actively working on disposal of empty, unused butane tank. Will continue trying to get this removed.

Unmarked tank/stored equipment



Debris/storage of equipment





## Zimmerman/Chamberlin

API 05-081-06668

Response to Field Insp 700704624 from Scott Ramsey/COGCC  
dated 10/21/2022



ROBERT L BAYLESS  
PRODUCER LLC

### BEFORE

- Load lines missing caps/plugs



**Load line missing cap/plug and manway is leaking  
with staining**

### AFTER





# Zimmerman/Chamberlin

API 05-081-06668

Response to Field Insp 700704624 from Scott Ramsey/COGCC  
dated 10/21/2022



ROBERT L BAYLESS  
PRODUCER LLC

## BEFORE

- Load lines missing caps/plugs (cont)



Load line missing cap/plug and debris



Load line missing cap/plug and some staining



Load line missing cap/plug

## AFTER





## Zimmerman/Chamberlin

API 05-081-06668

Response to Field Insp 700704624 from Scott Ramsey/COGCC  
dated 10/21/2022



ROBERT L BAYLESS  
PRODUCER LLC

### BEFORE

#### Equipment:

- Dead man not marked properly



Dead man not marked properly



Dead men not marked properly

### AFTER





## Zimmerman/Chamberlin

API 05-081-06668

Response to Field Insp 700704624 from Scott Ramsey/COGCC  
dated 10/21/2022

BEFORE


### Equipment:

- Dead man not marked properly (cont)



ROBERT L BAYLESS  
PRODUCER LLC

AFTER



### Storm Water:

- BMP's on cut slope are failing, cut slope not stabilized.



**BMP's Failing**

