

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403093402

Date Received:

06/30/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Jones, Tammy</u>		<u>tajones@hilcorp.com</u>
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693904557

Inspection Date: 05/24/2022

FIR Submit Date: 05/26/2022

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 306987

Location Name: ALLISON UNIT-N32N7W Number: 24NWNE County: LA PLATA
Qtrqr: NWNE Sec: 24 Twp: 32N Range: 7W Meridian: N
Latitude: 37.007310 Longitude: -107.555800

FACILITY - API Number: 05-067- -00 Facility ID: 289991

Facility Name: ALLISON UNIT Number: 147S
Qtrqr: NWNE Sec: 24 Twp: 32N Range: 7W Meridian: N
Latitude: 37.007310 Longitude: -107.555800

CORRECTIVE ACTIONS:

1 ☒ CA# 162294

Corrective Action: -Remove and properly store unused equipment offsite by 6/30/2022.

Date: 06/30/2022

Response: CA COMPLETED

Date of Completion: 06/29/2022

Operator Comment: We are currently testing the well to see if we can produce it without the pump unit . Production is not where it should be and it is very possible that the pump unit will be needed and put back in service.

COGCC Decision: **Not Approved**

COGCC Representative: Comment does not indicate that corrective action is addressed. Inspection conducted on 5/24 with corrective action date of 6/30, leaving a month to assess whether pump unit is needed. Pump should be removed and properly stored or put into use.

2 ☒ CA# 162295

Corrective Action: -Close and reclaim reclamation areas impacted by vehicle traffic and educate personnel to avoid driving on reclamation areas in order to prevent site degradation. Corrective action date 6/30/2022.

Date: _____

Response: CA COMPLETED

Date of Completion: 06/29/2022

Operator Comment: Wellhead barriers re installed.
Areas in the reclaimed area that were impacted by vehicle travel have been repaired.
Signs and fencing have been installed to keep vehicles off reclaimed areas.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions are resolved - see attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tammy Jones

Signed: _____

Title: Ops/Regulatory Tech

Date: 6/30/2022 7:42:01 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403093402	FIR RESOLUTION SUBMITTED
403093406	Resolved Photos

Total Attach: 2 Files