

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403227353

Date Received:
11/14/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>
.		<u>dnr_cogccenforcement@state.co.us</u>
		<u>daniel.gray@usda.gov</u>
<u>Toews, Wesley</u>		<u>wtoews@blm.gov</u>
		<u>geops@oxbow.com</u>
<u>Ferrin, Jeremy</u>		<u>jeremy.ferrin@state.co.us</u>
		<u>heather.lang@oxbow.com</u>
<u>Kosola, Jason</u>		<u>jason.kosola@state.co.us</u>
		<u>tyson.johnston@oxbow.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204280

Inspection Date: 11/01/2022

FIR Submit Date: 11/02/2022

FIR Status: _____

Inspected Operator Information:

Company Name: GUNNISON ENERGY LLC

Company Number: 10515

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 453805

Location Name: Trail Gulch Unit 1090 Number: 30 County: _____

Qtrqr: SWSE Sec: 30 Twp: 10S Range: 90W Meridian: 6

Latitude: 39.157036 Longitude: -107.477597

FACILITY - API Number: 05-051- -00 Facility ID: 453805

Facility Name: Trail Gulch Unit 1090 Number: 30

Qtrqr: SWSE Sec: 30 Twp: 10S Range: 90W Meridian: 6

Latitude: 39.157036 Longitude: -107.477597

CORRECTIVE ACTIONS:

1 CA# 165866Corrective Action: Date: 11/07/2022Response: CA COMPLETEDDate of Completion: 11/04/2022Operator Comment: COGCC Decision: Approved pending re-inspectionCOGCC Representative: 2 CA# 165867Corrective Action: Date: 06/18/2021Response: CA COMPLETEDDate of Completion: 11/14/2022Operator Comment: COGCC Decision: **Not Approved**COGCC Representative: 3 CA# 165868Corrective Action: Date: 05/21/2021Response: CA COMPLETEDDate of Completion: 11/09/2022Operator Comment: COGCC Decision: **Not Approved**COGCC Representative: 4 CA# 165869Corrective Action: Date: 11/04/2022Response: CA COMPLETEDDate of Completion: 11/01/2022Operator Comment:

COGCC Decision: **Not Approved**

COGCC Representative: CA required Operator to contact West Environmental Supervisor A. Fischer. Reclamation Staff confirmed with Environmental that GE has not contacted West Environmental Supervisor A. Fischer per the corrective action.

5  CA# 165870

Corrective Action: Comply with 1002.c and 1002.f; immediately remove soil stockpiles from the perimeter stormwater ditch and properly store. Implement BMPs in accordance with good engineering practices at all stockpiled soils to minimize erosion, degradation and sediment transport. Contact West Environmental Supervisor A. Fischer (alex.fischer@state.co.us) regarding possible additional Environmental requirements.

Date: 11/01/2022

Response: CA COMPLETED

Date of Completion: 11/03/2022

Operator Comment: Sample stockpiles removed and hauled to disposal facility. Awaiting sampling results and will consult with Mr. Fischer regarding any further actions upon receipt.

COGCC Decision: **Not Approved**

COGCC Representative: CA required Operator to contact West Environmental Supervisor A. Fischer. Reclamation Staff confirmed with Environmental that GE has not contacted West Environmental Supervisor A. Fischer per the corrective action.

6  CA# 165871

Corrective Action: Comply with 1002.f; implement BMPs at the excavated sample pits within ditch along east end of the Location, in order to prevent potential impacts to stormwater runoff/runoff.

Date: 11/01/2022

Response: CA COMPLETED

Date of Completion: 11/01/2022

Operator Comment: 10" sample holes were filled to remove hazard and prevent runoff into holes.

COGCC Decision: **Not Approved**

COGCC Representative: Though COGCC Staff appreciates the notice that Operator has taken steps to address the safety concerns regarding the observed "10" sample holes", this corrective action is regarding the excavated sample pits within the ditch along the east end of the Location, as stated within the corrective action and comment sections of the inspection reports.

OPERATOR COMMENT AND SUBMITTAL

Comment: Please call with any questions.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyson Johnston

Signed: _____

Title: Vice President

Date: 11/14/2022 10:05:02 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403227353	FIR RESOLUTION SUBMITTED
403227419	Wildlife Barrier
403227420	Topsoil Segregation from cut slope
403227422	Topsoil Stormwater 1
403227423	Topsoil Stormwater 2

403227425	Topsoil Stormwater 3
403227428	Topsoil Stormwater 4
403227434	Topsoil Stormwater 5

Total Attach: 8 Files