

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403197242

Date Received:

10/13/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Romana Cowden

Phone

720-951-5895

Email

COGCC.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204045

Inspection Date: 08/30/2022

FIR Submit Date: 09/02/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 441653

Location Name: Mesa Number: E1-797 County: _____

Qtrqr: SENW Sec: 1 Twp: 7S Range: 97W Meridian: 6

Latitude: 39.475967 Longitude: -108.173350

FACILITY - API Number: 05-045- -00 Facility ID: 441653

Facility Name: Mesa Number: E1-797

Qtrqr: SENW Sec: 1 Twp: 7S Range: 97W Meridian: 6

Latitude: 39.475967 Longitude: -108.173350

CORRECTIVE ACTIONS:

3 ☒ CA# 164316

Corrective Action: Comply with 1003.f. Additional monitoring/management efforts will be necessary in the 2023 growing season.

Date: 09/17/2022

Response: CA COMPLETED

Date of Completion: 09/06/2022

Operator
Comment:

Weeds were treated 9/06/2022. We will continue to monitor and treat in 2023.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

4 ☒ CA# 164317

Corrective Action: Comply with Rule 1002.f; install or repair stormwater and erosion control BMPs in accordance with good engineering practices; ensure BMPs are maintained in proper functioning condition until Location receives a passing final reclamation inspection.

Date: 09/09/2022

Response: CA COMPLETED

Date of Completion: 09/21/2022

Operator Comment: Repaired and seeded erosion throughout the fill slopes. Redefined pad perimeter diversion and installed perimeter berm along east edge of pad surface to split storm water flow to other control measures to minimize erosion on the fill slopes.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed, though it is unclear if BMPs are adequate to stabilize slopes, as well as to minimize erosion, degradation and sediment transport. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed:

Title: EHS

Date: 10/13/2022 4:27:47 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403197242	FIR RESOLUTION SUBMITTED
-----------	--------------------------

403197258	Erosion repaired/seeded.
-----------	--------------------------

Total Attach: 2 Files