



**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined:                      Pit ID: 257263              Lat: 37.123553              Long: -104.794067

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_                      Liner Condition: \_\_\_\_\_

Comment: The pit coordinates are incorrect.

Corrective Action

Operator shall provide a Form 15 pit report updating the latitude and longitude of the pit as specified in Rule 909.a.(2). In addition, the operator will complete the Operation Information and Conditions/Design & Construction tabs of the Form 15.

Date: 01/14/2023

**Fencing:**

Fencing Type: \_\_\_\_\_                      Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_                      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_      Oil Accumulation: \_\_\_\_\_      2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403227914	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5913713">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5913713</a>