

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403240141

Date Received:  
11/28/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Etta Trujillo</u>	<u>505-324-4145</u>	<u>etrujillo@logosresourcesllc.com</u>
<u>Dacye Shull</u>	<u>505-787-2027</u>	<u>dshull@logosresourcesllc.com</u>
<u>Vanessa Fields</u>	<u>505-787-2218</u>	<u>vfields@logosresourcesllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 702500563

Inspection Date: 10/07/2022

FIR Submit Date: 10/07/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

LOCATION - Location ID: 326440

Location Name: BONDAD 33-9-N33N9W Number: 8NENE County: LA PLATA

Qtrqtr: NENE Sec: 8 Twp: 33N Range: 9W Meridian: N

Latitude: 37.123010 Longitude: -107.843450

FACILITY - API Number: 05-067-00 Facility ID: 216494

Facility Name: BONDAD 33-9 Number: 25A

Qtrqtr: NENE Sec: 8 Twp: 33N Range: 9W Meridian: N

Latitude: 37.123010 Longitude: -107.843450

CORRECTIVE ACTIONS:

1 CA# 165133

Corrective Action: Install or repair/modify required BMPs per Rule 1002.f.(2)C, including ditches along access roads to minimize and control erosion and sediment migration.

Date: 11/07/2022

Response: CA COMPLETED

Date of Completion: 11/23/2022

Operator Comment: Required BMP's have been successfully repaired/modified per Rule 1002.f.(2)C. Photos attached

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Required BMP's have been successfully repaired/modified per Rule 1002.f.(2) Including repair of ditches along access roads to minimize and control erosion and sediment migration. 4 photos attached

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dacye Shull

Signed: \_\_\_\_\_

Title: Regulatory Technician

Date: 11/28/2022 9:26:36 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
403240153	Bondad 33-9 25A_photo1
403240154	Bondad 33-9 25A_photo2
403240155	Bondad 33-9 25A_photo3
403240156	Bondad 33-9 25A_photo4

Total Attach: 4 Files