

Inspection Photos

12/5/2022

Operator: PRE RESOURCES INC - 10241

Location #322302

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



Inspection Photos
Operator Name: PRE RESOURCES INC - 10241
Location #322302



Photo 1: Photos 1-2 taken from the west end of the Location. Photos provide an overview of the Location from north, northeast, southeast to south. Photos show final reclamation work including, but not limited too, compaction alleviation, recontouring, and reclamation has not been performed on the Location.

Inspection Photos
Operator Name: PRE RESOURCES INC - 10241
Location #322302



Photo 2: See comment under photo 1.

Inspection Photos
Operator Name: PRE RESOURCES INC - 10241
Location #322302



Photo 3: Photo taken from the south end of the Location, facing north. Photo shows final reclamation work including, but not limited too, compaction alleviation, recontouring, and reclamation has not been performed on the Location.

Inspection Photos
Operator Name: PRE RESOURCES INC - 10241
Location #322302



Photo 4: Photo shows soil stockpile (possibly topsoil?) that remains stored on the east end of the Location; site has not been recontoured/regraded and reclaimed.

Inspection Photos
Operator Name: PRE RESOURCES INC - 10241
Location #322302



December 5, 2022

Photo 5: Gully erosion/erosion degradation remains evident throughout the eastern areas of the Location, including the cut slopes.

Inspection Photos
Operator Name: PRE RESOURCES INC - 10241
Location #322302



December 5, 2022

Photo 6: Photo taken from the northeast end of the Location. Photo shows cut slope remaining. Photo also shows erosion degradation along the slopes.

Inspection Photos
Operator Name: PRE RESOURCES INC - 10241
Location #322302



Photo 7: Photos taken from the northeast end of the Location. Photo shows secondary containment berms for facilities on the Location remain evident, as well as gravel.

Inspection Photos
Operator Name: PRE RESOURCES INC - 10241
Location #322302



Photo 8: Photo shows remaining surface equipment on the Location.



Inspection Photos
Operator Name: PRE RESOURCES INC - 10241
Location #322302



December 5, 2022



December 5, 2022

Photo 9: Photos taken from the access road on the north end of the Location. Photo shows access road has not been reclaimed. Photo also shows erosion degradation has persisted.