

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/07/2022

Submitted Date:

12/08/2022

Document Number:

690203659**FIELD INSPECTION FORM**Loc ID 308888 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10351Name of Operator: WAPITI OPERATING LLCAddress: 1310 W SAM HOUSTON PKWY NCity: HOUSTON State: TX Zip: 77043**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mattorano, Michael		mmattorano@wapitienergy.com	
Madison, Randy		rmadison@wapitienergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284295	WELL	PR	06/14/2006	CBM	071-08769	VPR C 125	RI

**General Comment:**

This is a follow up of the previous reclamation inspections; #690201863, #690202101, #690202740, #690202865, #690203037, #690203239, #690203448.

The corrective action of the previous inspections has not been completed.  
See attached photos and additional details within this report.

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <span style="color: blue;">There is erosion along the main road in the canyon traveling to the location. There are multiple culverts filled in with sediment directing stormwater down the road causing erosion. Areas of erosion need to be repaired and stabilized. Previous corrective action was not completed. Corrective action must be performed immediately.</span>						Date: 09/01/2021
Corrective Action: <span style="color: red;">Install or repair required BMPs per Rule 1002.f.(2)C</span>						
<b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690203660	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5938604">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5938604</a>