

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403259115

Date Received:
12/13/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Andrew Olson	661-979-8847	andrewolson@chevron.com
Derek Eggert	510-571-1451	DHYG@chevron.com
John Cannon	985-276-7359	JFNM@chevron.com
Arthur, Denise		denise.arthur@state.co.us
Araza, Steven		steven.arauza@state.co.us
Fischer, Alex		alex.fischer@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203854

Inspection Date: 07/11/2022

FIR Submit Date: 07/15/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 324350

Location Name: SKINNER RIDGE-66S98W Number: 27NWSW County: _____

Qtrqr: NWS Sec: 27 Twp: 6S Range: 98W Meridian: 6
W

Latitude: 39.501400 Longitude: -108.324000

FACILITY - API Number: 05-045-00 Facility ID: 424210

Facility Name: SR Number: 698-21-01

Qtrqr: NWS Sec: 27 Twp: 6S Range: 98W Meridian: 6
W

Latitude: 39.501400 Longitude: -108.324000

CORRECTIVE ACTIONS:

1 CA# 163374

Corrective Action: Comply with 1003/1004 Reclamation Rules. Date: 09/01/2022
Ensure erosion controls are implemented per good engineering practices to stabilize the seeded soils, and continue to monitor and manage this site until Final Reclamation of the Facility has passed.

Response: CA COMPLETED Date of Completion: 12/01/2022

Operator Comment: Stormwater BMPs have been reinstalled. They are currently nested. Additional BMP's were installed to reinforce and augment previously installed storm water BMP's after seeding operations were completed.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 163375

Corrective Action: Comply with Rule 1002.f; implement and maintain site specific BMPs to control stormwater and minimize erosion, transport of sediment and degradation. Ensure BMPs are installed in accordance with good engineering practices and maintained in a proper functioning condition. Continue to monitor and manage stormwater until site receives a passing Final Reclamation inspection. Date: 07/30/2022

Response: CA COMPLETED Date of Completion: 12/01/2022

Operator Comment: Storm water BMP's (straw wattles) throughout the site. Summer rainstorms were server in this area and additional storm water mitigation BMP's have been installed. As spring thaw begins the site will be monitored for any signs of significant erosion. If erosion is present, it will be addressed by implementing additional erosion control methods.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Seed mixture tags are attached. Additional soil supplements were added at the time of seeding. The soil supplement information sheet is included. Responses to agent comments are also included in the attachment along with pictures of the location after seeding and mulching.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dawn Bittner Signed: _____

Title: Administrative Assistant Date: 12/13/2022 12:43:25 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403259141	Seed mixture, response to comments, pictures

Total Attach: 1 Files