

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403023475

Date Received:
04/21/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
.		regulatory@foundationenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 691200459
Inspection Date: 09/18/2018 FIR Submit Date: 09/19/2018 FIR Status: _____

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC Company Number: 10112
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 323513

Location Name: SOONER UNIT-68N58W Number: 28SWNE County: _____
Qtrqtr: SWNE Sec: 28 Twp: 8N Range: 58W Meridian: 6
Latitude: 40.634660 Longitude: -103.865830

FACILITY - API Number: 05-123-00 Facility ID: 323513

Facility Name: SOONER UNIT-68N58W Number: 28SWNE
Qtrqtr: SWNE Sec: 28 Twp: 8N Range: 58W Meridian: 6
Latitude: 40.634660 Longitude: -103.865830

CORRECTIVE ACTIONS:

1 CA# 118839

Corrective Action: Remove or remediate stained soil around wellsite and pump jack area.
Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 10/19/2018

Response: CA COMPLETED Date of Completion: 07/24/2019

Operator Comment: FIR Doc #696101217 states that this corrective action was addressed; stained soil around wellhead was mitigated. Follow up inspection date is entered as date of completion.

COGCC Decision: Approved

COGCC Representative: FIR Doc #696101217 dated 07/24/2019 states that this corrective action was addressed.

2 CA# 118840

Corrective Action: Remove unused equipment. Comply with Rule 603.f . Date: 10/19/2018

Response: CA COMPLETED Date of Completion: 07/24/2019

Operator Comment: FIR Doc #696101217 states that this corrective action was addressed; the unused equipment near the pumpjack was removed. Follow up inspection date is entered as date of completion.

COGCC Decision: Approved

COGCC Representative: FIR Doc #696101217 dated 07/24/2019 states that this corrective action was addressed.

3 CA# 118841

Corrective Action: Plumb bradenhead to surface.
Mechanical conditions (30 Days).
Securely fasten all valves, pipes, and fittings to ensure good mechanical condition,
inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Date: 10/19/2018

Response: CA COMPLETED Date of Completion: 07/24/2019

Operator Comment: FIR Doc #696101217 states that this corrective action was addressed; bradenhead was plumbed to surface. Follow up inspection date is entered as date of completion.

COGCC Decision: Approved

COGCC Representative: FIR Doc #696101217 dated 07/24/2019 states that this corrective action was addressed.

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action items have all been addressed. Please reference FIR Doc #696101217.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Afton Iiams Signed: _____

Title: HSE/Regulatory Technician Date: 4/21/2022 12:55:01 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403023475	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files