

RECEIVED

JAN 14 1971



00792356

OIL AND GAS CONSERVATION COMMISSION OF THE STATE OF COLORADO

File in duplicate for Patented and Federal lands.
File in triplicate for State lands.

COLO. OIL & GAS CONS. COMM.

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Frank H. Walsh

3. ADDRESS OF OPERATOR

Box 30, Sterling, Colorado 80751

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.)

At surface

900' N of S line

At proposed prod. zone 660' E of W line, Section 13, T3S, R59W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5169' K B

9. WELL NO.

#3

10. FIELD AND POOL, OR WILDCAT

Noonen RANCH

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 13-3S-59W

12. COUNTY OR PARISH

Adams

13. STATE

Colorado

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☒
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT

☐
☐
☐
☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work January 15, 1971

It is proposed to abandon the UPRR Noonen #3. It is intended to set cement (10 sks) across perfs. (6092-98). Fill hope with mud. Cmt across base of surface pipe w/5 sks, then 5 sks cmt @ surface and weld steel cap on surface pipe.

DVR	<input checked="" type="checkbox"/>
FJP	<input checked="" type="checkbox"/>
HHM	<input checked="" type="checkbox"/>
JAM	<input checked="" type="checkbox"/>
JJD	<input checked="" type="checkbox"/>

18. I hereby certify that the foregoing is true and correct

SIGNED

F H Walsh

TITLE

Owner

DATE

January 12, 1971

(This space for Federal or State office use)

APPROVED BY

M Rogers

TITLE

DIRECTOR

DATE

JAN 15 1971

CONDITIONS OF APPROVAL, IF ANY:

That a cement plug of at least 35 sks be placed from the base of the Fox Hills formation (+ 200') up into the base of the surface casing.