

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/06/2022

Submitted Date:

12/12/2022

Document Number:

707800004**FIELD INSPECTION FORM**Loc ID 335166 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

General Comment:**COGCC Inspection Report Summary**

On Monday 12/6/2022 at approximately 1100, I, Inspector Scott Ramsey, attempted to conduct a routine inspection at TEP Federal 31-01, at Location # 335166 in Garfield county Colorado.

Inspector did not access any locations. As per the signage at the locked gate.

While attempting to access location and multiple others entrance to all locations has signage noting no vehicle access during muddy conditions. It appeared that multiple vehicles have been accessing locations due to vehicle tracks. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

During this inspection the following compliance issues were observed:

1. Locations are not accessible during normal business hours.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Fail			

Comment: 1. Locations are not accessible during normal business hours.

Corrective Action: Repair and maintain lease road to comply with rule and maintain BMP's

Date: 01/23/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403259304	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5943002
707800010	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5942996