

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/12/2022

Submitted Date:

12/14/2022

Document Number:

697601984

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Ahmadian, Alexander On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	All Inspections
-, Marcom		primarycontractor@marcomllc.net	
Graber, Nikki		nikki.graber@state.co.us	
Meis, Craig		cmeis@kpk.com	KPK Environmental

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480994	SPILL OR RELEASE	CL	04/01/2022		-	UPRR 43 PAN AM I5	EI

General Comment:

This is an environmental inspection for Spill ID 480994 UPRR 43 PAN AM I5. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment: Signage is adequate at the wellhead.

Corrective Action:

Date: _____

Good Housekeeping:

Type WEEDS

Comment: Weeds are overgrown within the excavation.

Corrective Action: Comply with Rule 606

Date: 12/21/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type OTHER

Comment: Fencing around the excavation is inadequate.

Corrective Action: The operator is to maintain best management practices to control and contain all spills/releases of E&P waste to protect the environment, public health, safety and welfare and the environment as required by rule 913.b(5)B.i which requires that Operators will fence or cover open remediation excavations to prevent access when sites are not attended.

Date: 12/21/2022

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 480994 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403260724	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5944203
697601985	Photo Documentation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5944199