

7-8

FORM 17 Rev 11/20	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109		Document Number: <hr/>
BRADENHEAD TEST REPORT			

Step 1. Before opening any valves, record all tubing and casing pressures as found.
 Step 2. Collect liquid and gas samples as required; consult Bradenhead Testing and Reporting Instructions and Guidance for field specific Orders at <http://cogcc/reg.html#opguidance>
 Step 3. Conduct Bradenhead test.
 Step 4. Submit Form 17 within 10 days of test. Attach a wellbore diagram if not previously submitted or if wellbore configuration has changed since last wellbore diagram was submitted.
 Step 5. Submit sample analytical results via Form 43.

1. OGCC Operator Number: <u>51130</u>	3. BLM Lease No: <u>CD 24749</u>	11. Date of Test: <u>12/9/22</u>
2. Name of Operator: <u>Locin Oil Corporation</u>		12. Well Status: <u>Flowing</u>
4. API Number: <u>05-103-09225</u>	5. Multiple completion? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Shut In <input type="checkbox"/> Gas Lift <input type="checkbox"/>
6. Well Name: <u>Fork Unit</u>	Number: <u>7-B-21</u>	<u>Pumping</u> <input checked="" type="checkbox"/> Injection <input type="checkbox"/>
7. Location (QtrQtr, Sec, Twp, Rng, Meridian): <u>SWNE ... B 2S 101 W 6Pm</u>		Clock/Intermitter <input type="checkbox"/>
8. County <u>RIO BLANCO</u>	9. Field Name: <u>Fork Unit</u>	Plunger Lift <input type="checkbox"/>
10. Minerals: Fee <input type="checkbox"/> State <input type="checkbox"/> <u>Federal</u> <input checked="" type="checkbox"/> Indian <input type="checkbox"/>		13. Number of Casing Strings: <u>Two</u> <input checked="" type="checkbox"/> Three <input type="checkbox"/> Liner? <input type="checkbox"/>

14. EXISTING PRESSURES					
Record all pressures as found	Tubing: <u>0</u> Fm: _____	Tubing: _____ Fm: _____	Prod Csg <u>28</u> Fm: _____	Intermediate Csg: _____	Surf. Csg <u>D</u>

BRADENHEAD TEST

With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (Bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals.
 Describe character of flow in "Bradenhead Flow" column: O = No Flow; C = Continuous; D = Down to 0; S = Surge; W = Whisper
 Describe fluid type in "Bradenhead Fluid" column: H = Water H2O; M = Mud; G = Gas; V = Vapor; L = Liquid Hydrocarbon; H & M = Water & Mud; H & G = Water & Gas; H & V = Water & Vapor; M & G = Mud & Gas; M & V = Mud & Vapor; G & V = Gas & Vapor; H & L = Water & Liquid Hydrocarbon; M & L = Mud & Liquid Hydrocarbon; G & L = Gas & Liquid Hydrocarbon; V & L = Vapor & Liquid Hydrocarbon; N = None

Buried valve? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing	Prod Csg PSIG	Intermedia Csg PSIG	Bradenhead Flow:	Bradenhead Fluid:
Confirmed open? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	2:15	<input type="checkbox"/> D	<input type="checkbox"/>	28		O	N
BRADENHEAD SAMPLE TAKEN? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Gas <input type="checkbox"/> Liquid <input type="checkbox"/>	2:20	<input type="checkbox"/> O	<input type="checkbox"/>	28		O	N
Character of Bradenhead fluid: Clear Fresh Sulfur Salty Black Other:(describe) <u>NA</u>	2:25	<input type="checkbox"/> O	<input type="checkbox"/>	28		O	N
	2:30	<input type="checkbox"/> O	<input type="checkbox"/>	28		O	N
	2:35	<input type="checkbox"/> O	<input type="checkbox"/>	28		O	N
	2:40	<input type="checkbox"/> O	<input type="checkbox"/>	28		O	N
	2:45	<input type="checkbox"/> D	<input type="checkbox"/>	28		O	N
Instantaneous Bradenhead PSIG at end of test: > <u>0</u>							

7.8

INTERMEDIATE CASING TEST

With gauges monitoring production, intermediate casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals.

Describe character of flow in "Intermediate Flow" column: O = No Flow; C = Continuous; D = Down to 0; S = Surge; W = Whisper

Describe fluid type in "Intermediate Fluid" column: H = Water H2O; M = Mud; G = Gas; V = Vapor; L = Liquid Hydrocarbon; H & M = Water & Mud; H & G = Water & Gas; H & V = Water & Vapor; M & G = Mud & Gas; M & V = Mud & Vapor; G & V = Gas & Vapor; H & L = Water & Liquid Hydrocarbon; M & L = Mud & Liquid Hydrocarbon; G & L = Gas & Liquid Hydrocarbon; V & L = Vapor & Liquid Hydrocarbon; N = None.

Buried valve? Yes No	Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermediate Csg PSIG	Intermediate Flow:	Intermediate Fluid:
Confirmed open? Yes No		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
INTERMEDIATE SAMPLE TAKEN? Yes No Gas Liquid		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
Character of Intermediate fluid: Clear Fresh Sulfur Salty Black Other:(describe) _____		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>			
Instantaneous Intermediate Casing PSIG at end of test: > _____							

Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Test Performed By: LARRY CHRISTIAN Title: Pumper Phone: () 970-675-2439

Signed: Jerry W. Christian Title: Pumper Date: 12/19/22

Witnessed By: _____ Title: _____ Agency: _____