

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403270876

Date Received:

12/24/2022

Spill report taken by:

Spill/Release Point ID:

## SPILL/RELEASE REPORT (INITIAL /w SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

### OPERATOR INFORMATION

Name of Operator: EVERGREEN NATURAL RESOURCES LLC	Operator No: 10705	<b>Phone Numbers</b>
Address: 1875 LAWRENCE ST STE 1150		Phone: (719) 2204330
City: DENVER State: CO Zip: 80202		Mobile: ( )
Contact Person: Timothy Fernandez		Email: timothy.fernandeztj10@yahoo.com

☐ Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 403270876

Initial Report Date: 12/23/2022 Date of Discovery: 12/22/2022 Spill Type: Recent Spill

#### Spill/Release Point Location:

QTRQTR NWNW SEC 4 TWP 33S RNG 65W MERIDIAN 6

Latitude: 37.205570 Longitude: -104.682720

Municipality (if within municipal boundaries): County: LAS ANIMAS

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

#### Reference Location:

Facility Type: WELL SITE

☐ Facility/Location ID No

Spill/Release Point Name: Lazy Lizard 11-4

☒ Well API No. (Only if the reference facility is well) 05-071-06422☐ No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): Unknown

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): 0

Estimated Other E&amp;P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: 400 gal fresh water used by Fire Dept. to extinguish fire

Has the subject Spill/Release been controlled at the time of reporting? Yes

#### Land Use:

Current Land Use: NON-CROP LAND

Other(Specify):

Weather Condition: Clear, sub-zero temps.

Surface Owner: FEE

Other(Specify):

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Evergreen Natural Resources is notifying the COGCC of an incident which occurred on 12/23/2022 at approximately . ENR was notified of a fire located on the Lazy Lizard 11-4 Well location, API # 05-071-064220 Located in T 33S R 65W, section #4. What is known at this time, A fire started at the Engine Skid which caused minor damage to the Engine Skid and a wooden structure which was covering the engine. The Boncarbo Fire Department was contacted VIA 911 Dispatch and was able to extinguish the fire. Additionally, an ENR employee was onsite shortly after the fire started and was able to extinguish a small gas fire which started on the edge of the well location. The ENR employee also isolated the Engine Skid from the well head and Gathering System Immediately. There is an ongoing investigation to determine what the root cause of the fire was. No produced water was spilled. Approximately 400 gallons of fresh water was used to extinguish the fire. No foam was used.

**List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
12/22/2022	ENR		-	
12/22/2022	COGCC	Jason Kosola	-	Email
12/22/2022	LACOG	Robert Lucero	-	Email

**REPORT CRITERIA**

**Rule 912.b.(1) Report to the Director (select all criteria that apply):**

- No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.
- Waters of the State: n/a Public Water System: n/a
- Residence or Occupied Structure: n/a Livestock: n/a
- Wildlife: n/a Publicly-Maintained Road: n/a
- No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.
- No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.
- No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak
- Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)
- Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_
- Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_
- Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_
- Was there damage during excavation? \_\_\_\_\_
- Was CO 811 notified prior to excavation? \_\_\_\_\_
- No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.
- Estimated Volume of Impacted Solids (cu. yd.): \_\_\_\_\_
- No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:
- ☐ The presence of free product or hydrocarbon sheen Surface Water
- ☐ The presence of free product or hydrocarbon sheen on Groundwater
- ☐ The presence of contaminated soil in contact with Groundwater
- ☐ The presence of contaminated soil in contact with Surface water

Yes	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylights from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.
	<input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure:    ☐ Corrective Actions Completed (documentation attached, check all that apply)

☐ Horizontal and Vertical extents of impacts have been delineated.

☐ Documentation of compliance with Table 915-1 is attached.

☐ All E&P Waste has been properly treated or disposed.

☐ Work proceeding under an approved Form 27 (Rule 912.c).

Form 27 Remediation Project No: \_\_\_\_\_

☐ SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

### OPERATOR COMMENTS:

Evergreen Natural Resources is notifying the COGCC of an incident which occurred on 12/23/2022 at approximately . ENR was notified of a fire located on the Lazy Lizard 11-4 Well location, API # 05-071-064220 Located in T 33S R 65W, section #4. What is known at this time, A fire started at the Engine Skid which caused minor damage to the Engine Skid and a wooden structure which was covering the engine. The Boncarbo Fire Department was contacted VIA 911 Dispatch and was able to extinguish the fire. Additionally, an ENR employee was onsite shortly after the fire started and was able to extinguish a small gas fire which started on the edge of the well location. The ENR employee also isolated the Engine Skid from the well head and Gathering System Immediately. There is an ongoing investigation to determine what the root cause of the fire was. No produced water was spilled. Approximately 400 gallons of fresh water was used to extinguish the fire. No foam was used.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Timothy Fernandez

Title: Environmental Technician Date: 12/24/2022 Email: timothy.fernadeztj10@yahoo.com

COA Type	Description
0 COA	

## Attachment List

Att Doc Num	Name
403271198	PHOTO DOCUMENTATION

Total Attach: 1 Files

## General Comments

User Group	Comment	Comment Date
		Stamp Upon Approval

Total: 0 comment(s)