



August 9, 1957

Mr. Lewis J. Goldstein
Suite 309, Colo. Savings Bank Bldg.
Colo. Springs, Colo.

Dear Sir:

This is being written with reference to the No. 1 Robert L. Christian well with Mr. M. R. Voltz as the operator. The well is located in the SW SW of Section 12, 16S, 66W.

We have been requested by the bonding company to release the bond covering drilling operations on this well.

A check on the file of this well shows that we have not received a plugging report, or a completion report. This work must be completed before we can release the bond.

From an examination of the well site by our chief engineer, it was found that this well has not been properly plugged. Until the well is plugged we cannot release the bond.

Unless the well is properly plugged and the required forms filed, we will take the necessary legal action to complete the work.

Enclosed is a copy of the rules and regulations. I direct your attention to page 71, paragraph 100-6-21 (1).

Very truly yours,

OIL AND GAS CONSERVATION COMMISSION
OF THE STATE OF COLORADO

DVR:mmm

D. V. Rogers, Deputy Director