

HERBERT L. GOLDSTEIN  
309 COLORADO COMMERCIAL & SAVINGS BANK BLDG.  
104 SOUTH TEJON STREET  
COLORADO SPRINGS, COLORADO



00939297



March 24, 1959

OIL AND GAS CONSERVATION COMMISSION  
OF THE STATE OF COLORADO  
1162½ Elati Street  
Denver 4, Colorado

Attn: Mr. William R. Smith

Dear Mr. Smith:

Responsive to your letter of March 17th. I visited the well site on Sunday and have also checked with some of the men familiar with this drilling operation.

If you will recall, there was some question as to which was the well site. From the information I have obtained and from my memory, the actual well site was adjacent on the West to the two mud tanks and reservoir.

Upon checking this I find that no hole exists, only some old bracings that were there last year. This I filled to some extent Sunday leaving a lesser depression in the ground.

As to the hole, some 30 feet to the South, which was thought might possibly have been the original well, I find upon probing, that this hole was only some 20 to 30 feet deep. This I plugged with an additional 8 by 8 and filled to the surface. What this hole is nobody seems to know, but it definitely is not part of the original drilling operation.

HERBERT L. GOLDSTEIN  
309 COLORADO COMMERCIAL & SAVINGS BANK BLDG.  
104 SOUTH TEJON STREET  
COLORADO SPRINGS, COLORADO

2.

Incidentally, would you please check your records as to the name of this well. I believe you will find that it was the Robert Christian #1 and not Voltz # 1.

If this is not satisfactory, please contact me and I will abide by your wishes.

Very truly yours,



HERBERT L. GOLDSTEIN

HLG:gd