

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403279377

Date Received:  
01/04/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>.TEP</u>	<u>970-285-9377</u>	<u>COGCCInspectionReports@terraep.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 707800053  
Inspection Date: 12/21/2022 FIR Submit Date: 12/22/2022 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335283

Location Name: CLOUGH-66S94W Number: 20NWNW County: \_\_\_\_\_  
Qtrqr: NWN Sec: 20 Twp: 6S Range: 94W Meridian: 6  
W  
Latitude: 39.516159 Longitude: -107.919021

FACILITY - API Number: 05-045-00 Facility ID: 335283

Facility Name: CLOUGH-66S94W Number: 20NWNW  
Qtrqr: NWN Sec: 20 Twp: 6S Range: 94W Meridian: 6  
W  
Latitude: 39.516159 Longitude: -107.919021

CORRECTIVE ACTIONS:

1  CA# 166708

Corrective Action: Remove debris Date: 12/30/2022

Response: CA COMPLETED Date of Completion: 12/28/2022

Operator Comment: Production personnel were actively working on / repairing a separator at the time of the inspection. The old parts / fittings that were temporarily placed on the ground near the separator, have since been replaced and removed from the location. This corrective action is completed.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

--

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Production personnel were actively working on / repairing a separator at the time of the inspection. The old parts / fittings that were temporarily placed on the ground near the separator, have since been replaced and removed from the location. This corrective action is completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 1/4/2023 11:15:37 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

403279377	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files