

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/27/2022

Submitted Date:

12/30/2022

Document Number:

696204553**FIELD INSPECTION FORM**Loc ID 453726 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10163Name of Operator: NONSUCH NATURAL GAS INCAddress: P O BOX 110066City: NAPLES State: FL Zip: 34108**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccenforcement@state.co.us	
		dlee@nng.us.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453727	TANK BATTERY	AC	01/12/2018		-	CSOC 697-14 Tank Battery	RI

General Comment:

On 12/27/2022, Reclamation Specialist Trujillo inspected Nonsuch Natural Gas Incs CSOC TB Location in Garfield County, Colorado.

This inspection is a followup to:

#696201797 dated 9/16/2020;

#696201822 dated 9/24/2020;

#696201988 dated 11/02/2020;

#696202916 dated 7/12/2021;

#696203087 dated 8/23/2021;

#696203324 dated 11/1/2022;

#696203532 dated 3/28/2022;

and #696204030 to document compliance with the following corrective actions:

-Stormwater

This inspection is also a followup to corrective actions per NOAV #403100223

Limited visibility inspection due to snow cover, however no Resolution documents to report the completion of Corrective Actions have been submitted for prior Field Inspection Reports in accordance with Rule 210.b; Location remains out of compliance with COGCC Rules, corrective actions and abatement requirements.

Refer to the "Stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [See "COGCC Comments".](#)Corrective Action: **Install or repair required BMPs per Rule 1002.f.(2)C. Ensure control measures are installed in accordance with good engineering practices, and maintained in proper functioning condition.**

Date: 07/20/2021

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>STORWMATER</p> <p>Previous inspections observed that BMPs to protect and stabilize unpaved areas of the Location and access road, and to allow for proper stormwater discharge are missing, or insufficient; stormwater runoff resulted in erosion degradation and offsite sediment discharge at Location entrance and access road. Inspection required Operator to comply with Rule 1002.f.(2)C. NOAV #403100223 was issued 07/08/2022 also requiring compliance with Rules and corrective actions.</p> <p>Winter conditions prevented Reclamation Specialist from conducting an adequate stormwater inspection on the entire Location; however, no Resolution Form has been submitted by Operator to document that the corrective action per the NOAV, and prior inspections have been addressed. Original corrective action and date remains applicable.</p>	trujilloam	12/30/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403276187	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5965229
696204554	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5965220