

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403262667

Date Received:  
12/15/2022

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 22370  
Name of Operator: D & G ROUSTABOUT SERVICE

Address: 765 S 1/2 ROAD

City: MACK State: CO Zip: 81525

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

David Terrell

Phone

970-216-6929

Email

terrelloil@aol.com

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 696204445

Inspection Date: 12/03/2022

FIR Submit Date: 12/06/2022

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: D & G ROUSTABOUT SERVICE

Company Number: 22370

Address: 765 S 1/2 ROAD

City: MACK State: CO Zip: 81525

**LOCATION - Location ID: 322318**

Location Name: WEST SALT CREEK-  
FEDERAL-66S103W Number: 7NESW County: \_\_\_\_\_

Qtrqtr: NESW Sec: 7 Twp: 6S Range: 103W Meridian: 6

Latitude: 39.551413 Longitude: -108.922592

**FACILITY - API Number: 05-045- -00 Facility ID: 322318**

Facility Name: WEST SALT CREEK-  
FEDERAL-66S103W Number: 7NESW

Qtrqtr: NESW Sec: 7 Twp: 6S Range: 103W Meridian: 6

Latitude: 39.551413 Longitude: -108.922592

**CORRECTIVE ACTIONS:**

1 ☒ CA# 166426

Corrective Action: Maintain BMP to ensure containment integrity is not compromised; remove vegetation established within base, and on walls, of the containment BMP. Ensure containment is sufficient to contain 150% of the volume of the tank.

Date: 09/13/2022

Response: CA COMPLETED

Date of Completion: 09/12/2022

Operator  
Comment:

Weeds were chopped and removed from tank berm.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 ☒ CA# 166427

Corrective Action: Comply with Rule 606 and Rule 1003.f. Implement BMPs to prevent further spread and establishment of weeds on the Location, and to prevent weed/plant establishment around production equipment.

Date: 09/13/2022

Response: CA COMPLETED

Date of Completion: 09/12/2022

Operator Comment: Weeds were chopped and removed from location around the equipment and wellhead .

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: We were unaware that we needed to send reply after worked was completed.  
Due to plugging operations and weather, Inspector Aaron Trujillo was unable to do follow up inspection.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: David Terrell

Signed: \_\_\_\_\_

Title: Owner

Date: 12/15/2022 2:16:07 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403262667	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files