

OIL AND GAS CONSERVATION COMMISSION DEPARTMENT OF NATURAL RESOURCES OF THE STATE OF COLORADO

OCT - 7 1970



File in duplicate for Patented and Federal lands. File in triplicate for State lands.

COLO. OIL & GAS CONS. COMM.

5. LEASE DESIGNATION AND SERIAL NO. Colo. 04002-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL [X] GAS WELL [] OTHER []
2. NAME OF OPERATOR GASCO, INC.
3. ADDRESS OF OPERATOR 1600 Sherman Street, Denver Colo. 80203
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 200' WEL & 1526' SNL of Sec. 10 At proposed prod. zone NE SE NE
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 8029' G.L.
12. COUNTY Jackson 13. STATE Colo.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: TEST WATER SHUT-OFF [], PULL OR ALTER CASING [], FRACTURE TREAT [], MULTIPLE COMPLETE [], SHOOT OR ACIDIZE [], ABANDON [], REPAIR WELL [], CHANGE PLANS [], (Other) []
SUBSEQUENT REPORT OF: WATER SHUT-OFF [], REPAIRING WELL [], FRACTURE TREATMENT [], ALTERING CASING [], SHOOTING OR ACIDIZING [], ABANDONMENT [X], (Other) []
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work Completed 9-24-70

Plugged & Abandoned as follows:

1 Pulled 2-3/8" tubing and retrievable packer. Dump bailed 6 sx. of cement on bottom. Checked top of cement plug after set at 2042' depth with measuring line. Cut and pulled 5-1/2" casing at 1069' depth. Set 20 sx. cement plug thru tubing from 1110' to 1010' depth. Set 30 sx. cement plug thru tubing from 360' to 260' depth. Cemented in marker in top of 8-5/8" surface casing with 10 sx. Interval between plugs heavy mud.

Plugged and Abandoned 9-24-70.

Table with 4 rows and 2 columns: DVR, FJP, HHM, JAM. Checkmarks in the second column.

Ex Oil Prod.

18. I hereby certify that the foregoing is true and correct
SIGNED [Signature] TITLE Agent/GASCO, Inc. DATE 9-30-70

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE DIRECTOR DATE OCT 14 1970