

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403305097

Date Received:
01/27/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10690
Name of Operator: IMPETRO RESOURCES LLC
Address: 558 CASTLE PINES PKWY UNIT B-4
City: CASTLE PINES State: CO Zip: 80108

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Brent Bongers	3619355633	bbongers@impetroresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696105687
Inspection Date: 01/09/2023 FIR Submit Date: 01/19/2023 FIR Status:

Inspected Operator Information:

Company Name: IMPETRO RESOURCES LLC Company Number: 10690
Address: 558 CASTLE PINES PKWY UNIT B-4
City: CASTLE PINES State: CO Zip: 80108

LOCATION - Location ID: 317256

Location Name: STENNETT-62N49W Number: 15SEW County:
Qtrqr: SENW Sec: 15 Twp: 2N Range: 49W Meridian: 6
Latitude: 40.141750 Longitude: -102.844120

FACILITY - API Number: 05-121-00 Facility ID: 317256

Facility Name: STENNETT-62N49W Number: 15SEW
Qtrqr: SENW Sec: 15 Twp: 2N Range: 49W Meridian: 6
Latitude: 40.141750 Longitude: -102.844120

CORRECTIVE ACTIONS:

1 CA# 167084

Corrective Action: Properly dispose of oily waste in accordance with 905.e. Date: 02/03/2023

Response: CA COMPLETED Date of Completion: 02/03/2023

Operator Comment: will be completed

COGCC Decision:

COGCC
Representative: _____

2 CA# 167085

Corrective Action: Install sign to comply with Rule 605.d.

Date: 02/19/2023

Response: CA COMPLETED

Date of Completion: 02/19/2023

Operator
Comment: will be completed by date

COGCC Decision: _____

COGCC
Representative: _____

3 CA# 167086

Corrective Action: Comply with Rule 606.

Date: 01/27/2023

Response: CA COMPLETED

Date of Completion: 01/27/2023

Operator
Comment: Attempts made to remove vegetation. Due to recent blizzards and blowing/driftng snow it's too dangerous to move on equipment and have personnel on steep banks. Action item will be completed as soon as weather allows.

COGCC Decision: _____

COGCC
Representative: _____

4 CA# 167087

Corrective Action: Immediately install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective action date is the date the location was observed out of compliance.

Date: 01/09/2023

Response: CA COMPLETED

Date of Completion: 01/27/2023

Operator
Comment: Attempts made however, due to recent blizzards and blowing/driftng snow it's too dangerous to move on equipment and have personnel on steep banks. Action item will be completed as soon as weather allows.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brent Bongers

Signed: _____

Title: President/COO

Date: 1/27/2023 4:40:14 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files