

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403309121

Date Received:  
02/01/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800919

Inspection Date: 11/08/2022

FIR Submit Date: 11/14/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 478568

Location Name: FEDERAL Number: RWF 43-9 County: \_\_\_\_\_

Qtrqr: NESE Sec: 9 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.539414 Longitude: -107.885304

FACILITY - API Number: 05-045-

-00

Facility ID: 478568

Facility Name: FEDERAL Number: RWF 43-9

Qtrqr: NESE Sec: 9 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.539414 Longitude: -107.885304

CORRECTIVE ACTIONS:

1 CA# 166101

Corrective Action: Install or repair required BMPs per Rule 1002.f. Continue to monitor and manage stormwater on the Location. Ongoing stormwater management is required until the site receives a passing final inspection.

Date: 12/14/2022

Response: CA COMPLETED

Date of Completion: 11/21/2022

Operator Comment: All of the storm water issues identified in the FIR have been repaired / maintained. Additional gravel / rock has been added to the pad to help mitigate rutting. Corrective action complete.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: All of the storm water issues identified in the FIR have been repaired / maintained. Additional gravel / rock has been added to the pad to help mitigate rutting. Corrective action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 2/1/2023 12:26:05 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

|  |  |
|--|--|
|  |  |
|--|--|

Total Attach: 0 Files