

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403309160

Date Received:  
02/01/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
TEP		COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800931  
Inspection Date: 11/08/2022 FIR Submit Date: 11/14/2022 FIR Status:

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335613

Location Name: FEDERAL-66S94W Number: 11NWNW County:  
Qtrqr: NWN Sec: 11 Twp: 6S Range: 94W Meridian: 6  
W  
Latitude: 39.545044 Longitude: -107.861588

FACILITY - API Number: 05-045-00 Facility ID: 335613

Facility Name: FEDERAL-66S94W Number: 11NWNW  
Qtrqr: NWN Sec: 11 Twp: 6S Range: 94W Meridian: 6  
W  
Latitude: 39.545044 Longitude: -107.861588

CORRECTIVE ACTIONS:

2  CA# 166113

Corrective Action: Install proper guy line markers per Rule 1003.a or remove anchors if equipment unnecessary. Date: 11/28/2022

Response: CA COMPLETED Date of Completion: 11/17/2022

Operator Comment: Anchors were marked on 11/17/22. Corrective action complete.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

4  CA# 166184

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 11/09/2022

Response: CA COMPLETED

Date of Completion: 11/08/2022

Operator Comment: Pumper was dispatched to location and used vac-truck to evacuate all storm water from the well cellar immediately. The pumper discovered that a casing master valve had developed a small leak. The pumper re-packed the casing master valve with grease and successfully stopped the leak. Corrective action complete.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 2/1/2023 12:40:46 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403309160	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files