

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: _____ Pit ID: 257263 Lat: 37.123553 Long: -104.794067

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: The pit coordinates are incorrect. Previous corective action not completed.

Corrective Action Operator shall provide a Form 15 pit report updating the latitude and longitude of the pit as specified in Rule 909.a.(2). In addition, the operator will complete the Operation Information and Conditions/Design & Construction tabs of the Form 15.

Date: 01/14/2023

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403304851	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6000597
690203842	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6000593